

Affected Engines for Honda Service Bulletin # 56

BF 200A

- BAEJ 10000001 to approximately 1500116
- BAFJ 10000001 to approximately 1500116

BF 225A

- BAGJ 10000001 to approximately 1500324
- BAHJ 10000001 to approximately 1500022

