INSTRUCTION SHEET 319903 FOR 386651 LEVER, ROD & BELLCRANK PACKAGE

IMPORTANT: This parts package is used for service in place of 318171 Bellcrank, 318175 Rod, and 385657 Lever and Shaft on 1973-74 50 H.P. outboards. When any of these three parts need replacing, all the parts in this package must be used.

INSTRUCTION SHEET 319903 FOR 386651 LEVER, ROD & BELLCRANK PACKAGE

IMPORTANT: This parts package is used for service in place of 318171 Bellcrank, 318175 Rod, and 385657 Lever and Shaft on 1973-74 50 H.P. outboards. When any of these three parts need replacing, all the parts in this package must be used.





REVC

Printed in the United States. ©2004 BRP US Inc. All rights reserved. TM, ® Trademarks and registered trademarks of Bombardier Recreational Products Inc. or its affiliates.



Printed in the United States. ©2004 BRP US Inc. All rights reserved. TM, ® Trademarks and registered trademarks of Bombardier Recreational Products Inc. or its affiliates.



